

## **Examination of groundwater maintenance method accompanied with construction of underground structures. ( Part 1 )**

### **[ Point ]**

Constructions of linearly –shaped structures, such as large-sized trench roads may cause groundwater level change, which induces well drying and subsidence. We researched and organized the enforcement of previous groundwater environment assessment cases and countermeasure construction cases, clarified current problems, as well as proposed selection method of measure method.