

RECENT FLOODS IN JAPAN

HEAD, FLOOD DISASTER
PREVENTION DIVISION,
NILIM

TETSUYA NAKAMURA



**Levee breach in Sannjyou city
in Niigata pref.**



**Levee Breach in Nakanoshima
town in Niigata pref.**



Flood in Sannjyou city







Flood damage in Sannjyou city





Levee Breach in central Hukui city



Flood in central Hukui city



**Pump Car for mud
after flood**





**Separated Disposal after
flood**



Effect of high wave in Takamatsu city

High wave in central Takamatsu city



High wave overflow from river in Takamatsu city

High wave diffence succeeded in Horoshima city



Upstream flood damage



Broken piers of rail way



Drift woods after flood



**Entrance of underground spill way in
TOKYO**



Damage of facility for drinking water in MIYAZAKI city



Innundated hospital



Flood fighting in MIYAZAKI city